



Clio II Scénic

Laguna Espace

Type	S/Section		
CB0 M	07	10	11
JA0 C	07	10	11
JA1 B	07	10	11
X56 3 4 A Y	07	10	11
JE0 N	07	10	11

11

LOCKING TOOL TIGHTENING TORQUE SPECIFICATION FOR CAMSHAFT PULLEYS Mot. 1509
AND Mot. 1509-01

Other sub-sections concerned:


07

10

- Engine: F4P - F4R
- Gearbox: XXX

When fitting **Mot. 1509** and **Mot. 1509-01** (F4R engine), the gear wheels of **Mot. 1509** should be brought into contact with the camshaft pulleys, and the nuts (1) tightened to a torque of **8 daN.m**.

This will avoid the **Mot. 1509** gear wheels slipping onto the camshaft pulleys during removal-refitting.



"The repair methods given by the manufacturer in this document are based on the technical specifications current when it was prepared.

The methods may be modified as a result of changes introduced by the manufacturer in the production of the various component units and accessories from which his vehicles are constructed."

All copyrights reserved by Renault.

Copying or translating, in part or in full, of this document or use of the service part reference numbering system is forbidden without the prior written authority of Renault.