



Factory and fabrication cut-off S/Section

**CLIO
CLIO II
KANGOO
TWINGO**

See list below

17

equipped with D7F engines

17 STARTING IS DIFFICULT OR IMPOSSIBLE

O.T.S.: 0A30 MARK: F5

Other sub-section concerned: **12**

- Engines: **D7F**
- Gearbox: **XXX**

Basic manual:
Workshop Repair Manuals 295, 337, 325, 305.

LIST OF VEHICLES CONCERNED

VEHICLE	TYPE	From	To	VEHICLE	TYPE	From	To
CLIO	357 K	F 000004	F 091465	CLIO II (continued)	CB0 A	F 000001	F 101178
		H 000001	H 003847			W 000001	W 072408
		W 000001	W 056528			Y 000004	Y 050846
		Y 000001	Y 065534			F 000002	F 008382
	357 Y	F 000002	F 000329		CB0 F	W 000001	W 000002
		557 K	A 003453			A 004887	Y 011534
	557 K	F 000000	F 088609		SB0 A	F 000001	F 000001
		H 000001	H 008259			W 000002	W 003672
		W 000001	W 074486		SB0 F	W 000001	W 000005
		Y 000002	Y 069900			KANGOO	FC0 A
557 Y		F 000645	F 000667	FC0 F	U 000001		U 000010
657 K		A 000017	A 005326	KC0 A	U 000003		U 057657
	F 000001	F 021233	KC0 F	U 000001	U 000010		
	Y 000003	Y 000827	TWINGO	C06 6	F 000009	F 652024	
CLIO II	BB0 A	F 000001		F 106039	W 000001	W 094189	
		W 000001		W 181264	C06 7	F 000001	F 079622
		Y 000048		Y 073318	C06 8	F 000002	F 354125
	BB0 F	F 000002		F 005240	S06 6	F 000001	F 145263
		W 000001		W 000004	W 000007	W 001482	
		Y 000002	Y 012384				

"The repair methods given by the manufacturer in this document are based on the technical specifications current when it was prepared.

The methods may be modified as a result of changes introduced by the manufacturer in the production of the various component units and accessories from which his vehicles are constructed."

All copyrights reserved by Renault.

Copying or translating, in part or in full, of this document or use of the service part reference numbering system is forbidden without the prior written authority of Renault.

CUSTOMER COMPLAINT

- Starting is difficult or impossible

POSSIBLE CAUSE

- Bosch injectors jammed following fuel development.

CLAIM COMPLETION AND CODING

Destination of removed parts:

- For UK, return to COMEX, Swindon.

Accounts procedure:

- Request for reimbursement or individual claim, depending on the country.
- Expense Code: **91**
- Parts at cost price.
- Labour at contractual warranty rate.
- Closure date: **31/12/2003.**

O.T.S. code: **0A30** (0 = figure zero)

Breakdown charge:

Code: DE Workshop repair
DT External repair

Towing charge:

Code: RE Towing by dealership
RT Non-Renault towing

– *CLIO*

Operation code: 1887
Time allowed: 0.5 hour

– *CLIO II and KANGOO*

Operation code: 1319
Time allowed: 0.5 hour

– *TWINGO*

Operation code: 1234
Time allowed: 0.5 hour

AFTER-SALES SOLUTION

Operation to be carried out:

- Identification of the injector manufacturer and replacement of BOSCH injectors.

Vehicles concerned:

- See vehicle types and fabrication cut-offs shown on title page.

When to take action:

- Upon receipt of a customer complaint.

Parts required:

- 4 SIEMENS injectors

Part No.: 77 00 874 112

Tooling required:

- Conventional.

Description of the operation:

- Identification of the injector manufacturer.
BOSCH injectors: pink collar
SIEMENS injectors: violet collar

If BOSCH injectors

- Replace the BOSCH injectors with SIEMENS injectors.

Marking the vehicle after the work has been carried out:

- Affix a blue label to the driver's side front shock absorber turret (specific to MULTIVERSION)
Part no. : 49 39 031 079.
- Mark a cross in square **F5** using a marker pen.

	1	2	3	4	5	6
F					X	
G						
H						
I						
J						
K						

For UK Market: Mark a cross in square **F5** using a marker pen.

NOTE: On current vehicles the matrix box is printed at the rear of the Service booklet.

In absence of the matrix box, affix a blue label, **Part No: 49 39 031 070**, to the rear inside cover of the Service booklet. Transfer previously marked squares to the new label and remove and destroy the old label.