



# CLIO 2

List below

*fitted with a rain sensor*

**84A** **AUTOMATIC WINDSCREEN WIPER TRIGGERING DOES NOT WORK OR OPERATES RANDOMLY**

Other sub-section concerned:

**54A**

**85A**

- Engine: **XXX**
- Gearbox: **XXX**

Basic manual:  
Workshop Repair Manual: **338, 345**

**LIST OF VEHICLES LIKELY TO BE AFFECTED**

Vehicle type	Type	from	to
<b>CLIO 2</b>	BB0 5	W 000001	W 001644
	BB0 7	W 000001	W 048103
	BB0 P	W 000001	W 030086
	BB1 3	W 000001	W 000171
	BB1 D	W 000001	W 000967
	BB1 L	W 000001	W 007939
	BB2 C	W 000001	W 004511
	BB2 D	W 000001	W 004096

Vehicle type	Type	from	to
<b>CLIO 2</b>	CB0 5	W 000001	W 006874
	CB0 7	W 000001	W 029844
	CB0 P	W 000001	W 025069
	CB1 D	W 000001	W 001673
	CB1 L	W 000001	W 004078
	CB2 C	W 000001	W 000714
	CB2 D	W 000001	W 002250
	SB0 7	W 000001	W 034252

"The repair methods given by the manufacturer in this document are based on the technical specifications current when it was prepared.

The methods may be modified as a result of changes introduced by the manufacturer in the production of the various component units and accessories from which his vehicles are constructed."

All copyrights reserved by RENAULT.

Copying or translating, in part or in full, of this document or use of the service part reference numbering system is forbidden without the prior written authority of RENAULT.

### CUSTOMER COMPLAINT

- Automatic windscreen wiper triggering does not work or operates randomly.

### POSSIBLE CAUSE

- No rain sensor window on the windscreen.

### FAULT FINDING

- Confirm the customer complaint.
- Check the windscreen supplier code located inside the Renault card on the lower right-hand section. This Technical Note applies if the supplier code is 573.

### CLAIM COMPLETION AND CODING

#### Destination of removed parts:

- As per Warranty Policy and Procedures Manual.

- **Without PG&CS**

**NITG code:** V321

- **With PG&CS**

**Catalogue function:** 009

**Cause reference:** 77 01 473 627

- **With or without PG&CS**

**Supplier code:** 573

**Customer complaint code:** 7P

**Operation code:** 5021

**Total time allowed:** 1.5 h

### AFTER-SALES SOLUTION

#### Operation to be carried out:

- Replace windscreen.

#### Vehicles affected:

- Types and cut-offs listed on the title page fitted with rain sensor.

#### When to take action:

- Upon receipt of a customer complaint.

#### Parts required:

Quantity and description of parts		Part No.
1	windscreen	77 01 473 627

#### Tooling required:

- Conventional.

#### Description of the operation:

- Replace the windscreen according to Workshop Repair Manual 338.