



CLIO II

Type

S/Section

XB0 X

33

fitted with TRW rear brake drums

33 REAR WHEELS LOCK AFTER BUILD UP OF SNOW

- Engine: XXX
- Gearbox: XXX

Basic manual:

Workshop Repair Manual 337

Cancel and replaces Technical Note no. 4040E dated NOVEMBER 2000

Modification: Part numbers required

CUSTOMER COMPLAINT

- Rear wheels lock after build up of snow.

POSSIBLE CAUSE

- Ice has entered the rear brake drums.

CLAIM COMPLETION AND CODING

Destination of removed parts:

- As per Warranty Policy and Procedures Manual.

Without Warranty Policy and Service Contract

NITG code: L145

With Warranty Policy and Service Contract

Catalogue function: 053

Cause reference:

Version with ABS: 77 01 050 187
Version without ABS: 77 01 050 189

Supplier code: 376

Customer complaint code: 7P

Operation codes: 3999+3156+0129

Time allowed: 1.7 h

AFTER-SALES SOLUTION

Operation to be carried out:

- Replacement of rear braking plates.

Vehicles concerned:

- All CLIO IIs.

When to take action:

- Upon receipt of a customer complaint.

Parts required:

Version with ABS

- 1 left rear brake backing plate **Part no.: 77 01 050 187**
- 1 right rear brake backing plate **Part no.: 77 01 050 188**

Version without ABS

- 1 left rear brake backing plate **Part no.: 77 01 050 189**
- 1 right rear brake backing plate **Part no.: 77 01 050 190**

All versions

- 2 rear hub nuts **Part no.: 77 03 034 118**
- 8 rear backing plate bolts **Part no.: 77 00 756 616**
- 8 rear backing plate washers **Part no.: 77 03 055 011**
- 1 can of brake fluid **Part no.: 77 11 172 381**

Tooling required:

- Conventional.

Description of the operation:

- Replace the rear brake backing plates.

"The repair methods given by the manufacturer in this document are based on the technical specifications current when it was prepared.

The methods may be modified as a result of changes introduced by the manufacturer in the production of the various component units and accessories from which his vehicles are constructed."

All copyrights reserved by Renault.

Copying or translating, in part or in full, of this document or use of the service part reference numbering system is forbidden without the prior written authority of Renault.