



CLIO II

List below

33

33 COLLAPSE OF THE REAR SUSPENSION

O.T.S.: 0A0F MARK: E1

Other sub-section concerned:

09

- Engine: **XXX**
- Gearbox: **XXX**

Basic manual:

Repair manual 337

TYPE	From	To	TYPE	From	To
BB0 A	F 000001	F 046216	CB0 A	F 000001	F 037566
	W 000001	W 057811		W 000001	W 032627
	Y 000001	Y 026080		Y 000001	Y 016781
BB0 C	F 000001	F 017072	CB0 C	F 000001	F 011221
	W 000001	W 022986		W 000001	W 010637
	Y 000001	Y 010661		Y 000001	Y 005278
BB0 D	F 000001	F 009981	CB0 D	F 000001	F 005886
	W 000001	W 014001		W 000001	W 004531
	Y 000001	Y 004501		Y 000001	Y 001692
BB0 E	F 000001	F 023606	CB0 E	F 000001	F 005903
	W 000001	W 026087		W 000001	W 011135
	Y 000001	Y 006325		Y 000001	Y 001758
BB0 F	F 000001	F 005213	CB0 F	F 000001	F 008357
	W 000001	W 000014		Y 000001	Y 002307
	Y 000001	Y 002081		CB0 L	F 000001
BB0 L	F 000001	F 000004	CB0 S	F 000001	F 000005
BB0 S	F 000001	F 000014		W 000001	W 000004
BB0 U	F 000001	F 000007	CB0 T	F 000001	F 000557
				Y 000001	Y 000002
			SB0 A	W 000001	W 000624
			SB0 E	F 000001	F 000002
				W 000001	W 009719
			SB0 R	F 000001	F 000002
				W 000001	W 002342

"The repair methods given by the manufacturer in this document are based on the technical specifications current when it was prepared.

The methods may be modified as a result of changes introduced by the manufacturer in the production of the various component units and accessories from which his vehicles are constructed."

All copyrights reserved by Renault.

Copying or translating, in part or in full, of this document or use of the service part reference numbering system is forbidden without the prior written authority of Renault.

REAR AXLE ELEMENTS

Spring

33

CUSTOMER COMPLAINT

- Noise coming from the rear of the vehicle.

POSSIBLE CAUSE

- Breaking of a rear suspension spring.

CLAIM COMPLETION AND CODING

Destination of removed parts:

- Scrap in accordance with dealer/importer instructions.

Accounts procedure:

- Request for reimbursement or individual claim, depending on the country.
- Expense code: **91**
- Parts at cost price.
- Labour at contractual warranty rate.
- Closure date: **31/12/2002.**

O.T.S. Code: **0A0F** (0 = figure zero)

Customer Complaint Code: **7 L**

Operation Code: **3380**

Time allowed: **0.6 hours**

AFTER-SALES SOLUTION

Operation to be carried out:

- Replacement of the two rear suspension springs.

Vehicles concerned:

- See vehicle types and production run details on page 1.

When to take action:

- Upon receipt of a customer complaint.

Parts required:

- Two suspension springs according to colour:
 - red **Part no.: 77 00 839 337**
 - green **Part no.: 77 00 419 364**
 - purple **Part no.: 77 00 839 338**
 - yellow **Part no.: 77 00 430 890**
 - grey **Part no.: 77 00 274 094**

Tooling required:

- Conventional.

Description of the operation:

- Replacement of the two rear suspension springs

Marking the vehicle after the work has been carried out:

- Affix a blue label, **Part No.: 49 39 031 070**, to the driver's side front shock absorber turret.
- Mark a cross in square **E1** using a marker pen.

	1	2	3	4	5	6
A						
B						
C						
D						
E	X					

NOTE: The label, Part No.: **49 39 031 070**, is available in sheets of 10 labels (delivered in packs of 10 sheets).