



Factory and fabrication cut-off S/Section

CLIO II

List below

36

fitted with SMI power assisted steering

36 STEERING CREAKS WHEN TURNED

Other sub-section concerned: 09

- Engine: **XXX**
- Gearbox: **XXX**

Basic manual:
Repair manual 337

LIST OF VEHICLES CONCERNED

TYPE	From	To	TYPE	From	To	TYPE	From	To			
BB0 A	F 080657	F 096950	CB0 A	F 076263	F 092525	SB0 A	W 002493	W 003174			
	W 137269	W 163953		CB0 D	F 019333		F 019712	SB0 E	F 003628	F 005551	
	Y 053180	Y 064676			CB0 E		W 023091		W 024876	SB0 J	W 034845
BB0 D	F 030158	F 034179	CB0 F			Y 004157	Y 004545		SB0 R		F 000098
	W 032043	W 036924		CB0 J		Y 014752	Y 018537	SB0 R			F 001481
	Y 007692	Y 008033			CB0 L	F 002917	F 004149			SB0 R	W 015777
BB0 E	W 061606	W 066999	CB0 M			W 002528	W 004357		SB0 R		
	Y 012909	Y 013285		CB0 S		Y 000122	Y 000714	SB0 R			
	BB0 F	Y 010804			Y 013589	CB0 T	F 000384			F 005734	SB0 R
BB0 J		F 012508	F 020248		CB0 U		W 003636		W 008913	SB0 R	
		W 010224	W 018061	CB0 U			Y 000030	Y 001031	SB0 R		
	Y 000455	Y 002494	CB0 U			K 000017	K 003430	SB0 R			
BB0 L	F 001497	F 008231			CB0 U	Y 000001	Y 000031			SB0 R	
	W 003049	W 011018		CB0 U		F 007095	F 011139		SB0 R		
	Y 000060	Y 002242	CB0 U			W 009176	W 012117	SB0 R			
BB0 S	F 015618	F 021606			CB0 U	Y 010172	Y 014122			SB0 R	
	W 026240	W 036638		CB0 U		F 014153	F 017575		SB0 R		
	Y 018844	Y 028517	CB0 U			W 000006	W 000282	SB0 R			
BB0 T	F 000217	F 002258			CB0 U	Y 000003	Y 000114			SB0 R	
	W 000006	W 000717		CB0 U		F 000212	F 001861		SB0 R		
	Y 000004	Y 000335	CB0 U			W 000013	W 004569	SB0 R			
BB0 U	F 000246	F 006225			CB0 U	Y 000001	Y 000291			SB0 R	
	W 000014	W 008617		CB0 U					SB0 R		
	Y 000001	Y 000653	CB0 U					SB0 R			

"The repair methods given by the manufacturer in this document are based on the technical specifications current when it was prepared.

The methods may be modified as a result of changes introduced by the manufacturer in the production of the various component units and accessories from which his vehicles are constructed."

All copyrights reserved by Renault.

Copying or translating, in part or in full, of this document or use of the service part reference numbering system is forbidden without the prior written authority of Renault.

CUSTOMER COMPLAINT

- Power assisted steering creaks when wheel turned.

POSSIBLE CAUSE

- Power assisted steering rack fixing.

CLAIM COMPLETION AND CODING

Destination of removed parts:

- As per Warranty Policy and Procedures Manual.

NITG code: L212

Supplier code: 373

Customer complaint code: 2C

Operation code: 3999

Time allowed: 0.8 hour

AFTER-SALES SOLUTION

Operation to be carried out

- Replace the power assisted steering rack bearing mounting on the valve side.

Vehicles concerned:

- All CLIO II models fitted with SMI power assisted steering and manufactured between January and May 2000.

When to take action:

- Upon receipt of a customer complaint.

Part required:

- 1 power assisted steering rack bearing

Part number: 82 00 124 590

Incorporating:

- 1 metal flange,
- 1 aluminium mounting,
- 1 rubber filter,
- 1 bolt,
- 1 nut.

Tooling required:

- Conventional.

Description of the operation:

- Remove and refit the power assisted steering rack bearing on the valve side using the above items
Part number: 82 00 124 590 (See Workshop Repair Manual 337).