



CLIO 2 RS

Type

Production cut-offs

CB0 M	K 000001 to K 006957
	Y 000001 to Y 002504
CB1 5	K 000001 to K 029900
CB1 C	K 000001 to K 002188
	Y 000001 to Y 002058
CB1 G	K 000001 to K 029857
CB1 N	K 000001 to K 029899
	Y 000001 to Y 073414
CB1 S	K 000001 to K 000095
CB1 T	K 000001 to K 029588

with F4R engine

Cancels and replaces Technical Note No. 4296A dated NOVEMBER 2002.

Modifications: changes to technical solution

10A ACCESSORIES BELT SLIPS OFF: ENGINE NOISE AND WARNING LIGHT COMES ON

Other sub-section concerned:

09A

11A

16A

36B

83A

- Engine: **F4R 730 - 732 - 736**
- Gearbox: **XXX**

Basic manual:

Technical Note: **3286A, 3328A**

TECHNICAL INFORMATION

Customer complaint

- Charge warning light comes on.
- Engine noise.

Possible cause

- Accessories belt jumping.

Fault finding

- Check the presence and condition of the accessories belt.

"The repair methods given by the manufacturer in this document are based on the technical specifications current when it was prepared.

The methods may be modified as a result of changes introduced by the manufacturer in the production of the various component units and accessories from which his vehicles are constructed".

All copyrights reserved by RENAULT.

Copying or translating, in part or in full, of this document or use of the service part reference numbering system is forbidden without the prior written authority of RENAULT.

Description of the operation

WARNING

When removing parts for replacement, check the part number written on the label on the power assisted steering pump body.

- Replace:
 - the accessories belt,
 - the adjustable tensioner,
 - the air conditioning compressor mounting,
 - the air conditioning compressor,
 - the power assisted steering pump if the part number is different to **82 00 234 212**.

WARNING


Follow the instructions in Technical Note 3286A when fitting and Technical Note 3328A when adjusting.

- Use a set of feeler gauges to measure gap (X) between the accessories belt and the adjustable tensioner body.

WARNING

Gap (X) between the accessories belt and the adjustable tensioner body **MUST** be at least **3 mm**. If gap (X) is smaller than **3 mm**: fit a new accessories belt and check again.

- Perform a basic road test.



X – Gap value at least **3 mm**

CLAIM COMPLETION AND CODING

When to take action

- Upon receipt of a customer complaint.

Parts required

Quantity and description of parts	Part No.
1 Accessories belt	82 00 226 493
1 Adjustable tensioner	82 00 226 495
1 Air conditioning compressor	60 00 073 500
1 Air conditioning compressor mounting	77 00 864 098
1 M8 40 collar screw	77 03 002 419
1 8.2 Plain washer	77 03 053 596

Including replacement of the power assisted steering pump

Quantity and description of parts	Part No.
1 Power assisted steering pump	82 00 234 212

Description	Various codes
Power assisted steering fluid (1.1 litres)	LU

Tooling required

- Conventional.
- Air conditioning filling station.

Time required

Code	Description	Time
0168	Multifunction support replacement	3.4
0129	Basic road test	0.5
TOTAL		3.9

Component codification

• With PGCS

- Catalogue function:

Description	Code
Alternator, starter, pulley and belt	118

- Cause reference: **77 00 864 098**

• Without PGCS

- NITG code: **G334**

• With or without PGCS

- Supplier code: **X22**
- Customer complaint code: **1C, 2C**