



Twingo Kangoo

Clio

Mégane

Laguna

Espace

Type		S/Section	
X06	8CD6JK	12	17
XC0	15BFLMP	12	17
XC0	STW3	12	17
XB0	35BFHL	12	17
XB0	PTW	12	17
XB1	013457	12	17
XB1	8DGK	12	17
XB1	LNSTV	12	17
XB2	B	12	17
XA0	34BCDPW	12	17
XA1	01234AD	12	17
XA1	GHJLMRS	12	17
XG0	16ABCDJ	12	17
XG0	KLMNSUVY	12	17
XE0	02LNTUV	12	17

12 MOTORIZED THROTTLE BODY

Other sub-sections concerned: 17

- Engine: XXX EURO 2000 and IF 2005
- Gearbox: XXX

We inform you that none of the motorized throttle can be repaired.

After removal of the motorized throttle body, it is absolutely forbidden to:

- modify the position of the stop screws,
- open the throttle body.

"The repair methods given by the manufacturer in this document are based on the technical specifications current when it was prepared.

The methods may be modified as a result of changes introduced by the manufacturer in the production of the various component units and accessories from which his vehicles are constructed."

All copyrights reserved by Renault.

Copying or translating, in part or in full, of this document or use of the service part reference numbering system is forbidden without the prior written authority of Renault.