



CLIO II

See list below

03

Cancels and replaces Technical Note No. 3130A of November 1998
Modifications : Extension of vehicle ranges

03 TOWING HOOK

O.T.S. : 0086 MARKING: B6

Other sub-section concerned:

999

- Engine: XXX
- Gearbox: XXX Basic manual: XXX

LIST OF VEHICLES CONCERNED

TYPE	from	to	TYPE	from	to
BB0 A	F 000001	F 015005	CB0 A	F 000001	F 010019
	W 000001	W 016519		W 000001	W 012678
	Y 000001	Y 000862		Y 000001	Y 000135
BB0 C	F 000001	F 006068	CB0 C	F 000001	F 002853
	W 000001	W 005856		W 000001	W 004195
	Y 000001	Y 000211		Y 000001	Y 000009
BB0 D	F 000001	F 002853	CB0 D	F 000001	F 001136
	W 000001	W 002333		W 000001	W 001290
	Y 000001	Y 000390		Y 000001	Y 000018
BB0 E	F 000001	F 008075	CB0 E	F 000001	F 001777
	W 000001	W 004855		W 000001	W 003342
	Y 000001	Y 000394		Y 000001	Y 000038

"The repair methods given by the manufacturer in this document are based on the technical specifications current when it was prepared.

The methods may be modified as a result of changes by the manufacturer in the production of the various component units and accessories from which his vehicles are constructed".

All copyrights reserved by Renault.

Copying or translating, in part or in full, of this document or use of the service part reference numbering system is forbidden without the prior written authority of RENAULT.



SUBJECT

Preventive operation :

- Replacing the towing ring.

CLAIM COMPLETION AND CODING

Destination of removed parts :

- **Outside of FRANCE** : return to your local After Sales Head Office (or Importer). For UK Market, return to Comex, Swindon.

Accounts procedure :

- Request for reimbursement or individual claim, depending on country.
- Nature of expense : O.T.S. (FRANCE)
- Expense Code : 91 (Outside FRANCE)
- Parts at cost price.
- Labour at contractual warranty rate.
- Closure date : Unlimited.

O.T.S. Code : 0086

Customer Complaint Code : 5P

Operation Code : 5999

Time allowed : 0.2 hours

Description : Replacing the towing ring.

AFTER SALES SOLUTION

Operation to be carried out :

- Replacing the towing ring.

Vehicles concerned :

- Vehicle types and fabrication ranges shown on title page.

When to take action :

- Upon first visit to the workshop and/or by customer letter.

Parts required :

Depending on availability :

- 1 towing ring Part No. : 77 00 419 544,
or Part No. : 77 00 434 256.

Tooling required :


- None.

Description of operation :

- Replace the towing ring (the towing ring is located underneath the carpet in the tool tray on top of the spare wheel).

Marking the vehicle after the work has been carried out:

- Affix a **BLUE** label Part No : **49 39 031 070** to the driver's side front shock absorber turret.
- Mark a cross in square **B6** using a marker pen.



ITC201584

Fig. 1

For UK Market :

Mark a cross in square **B6** using a marker pen.

NOTE: On current vehicles the matrix box is printed at the rear of the Warranty and Servicing booklet.

	1	2	3	4	5	6
A						
B						X
C						
D						
E						

NOTE :

The label, Part No : **49 39 031 070** is available in sheets of 10 labels (delivered in packs of 10 sheets).