



Specific to: *Countries with right-hand drive vehicles*

Factory and fabrication cut-off

S/Section

CLIO II

List below

37

right-hand drive

37 ACCELERATOR CABLE (RIGHT-HAND DRIVE VEHICLES)

OTS: 0A2M MARK : F1

Other sub-section concerned:

999

- Engine: **XXX**
- Gearbox: **XXX**

Basic manual:

Workshop Repair Manual 337

LIST OF VEHICLES CONCERNED

TYPE	from	to	TYPE	from	to
BB0 A	F 001325	F 083666	CB0 A	F 000150	F 076453
BB0 C	F 000466	F 020345	CB0 C	F 000083	F 012819
BB0 D	F 000252	F 031849	CB0 D	F 000059	F 019296
BB0 E	F 000110	F 038587	CB0 E	F 000395	F 009591
BB0 J	F 000014	F 012051	CB0 J	F 000003	F 002621
BB0 L	F 000593	F 001496	CB0 L	F 000175	F 000746
BB0 S	F 000001	F 017083	CB0 S	F 000002	F 006932
BB0 T	F 000010	F 000211	CB0 T	F 000046	F 013987
BB0 U	F 000005	F 000535			
			SB0 E	F 000001	F 000778
			SB0 J	F 000002	F 000062

"The repair methods given by the manufacturer in this document are based on the technical specifications current when it was prepared.

The methods may be modified as a result of changes introduced by the manufacturer in the production of the various component units and accessories from which his vehicles are constructed."

All copyrights reserved by Renault.

Copying or translating, in part or in full, of this document or use of the service part reference numbering system is forbidden without the prior written authority of Renault.

SUBJECT

Preventive operation:

- Replacement of the accelerator cable.

CLAIM COMPLETION AND CODING

Destination of removed parts:

- **FRANCE:** MUST return to **SRPG**.
- For UK, return to COMEX, Swindon.

Accounts procedure:

- Request for reimbursement or individual claim, depending on the country.
- Expense code: **91**
- Parts at cost price.
- Labour at contractual warranty rate.
- Closure date: **unlimited**.

OTS code: **0A2M** (0 = figure zero)

Operation code: **3153**

Time allowed: **0.5 h**

AFTER-SALES SOLUTION

Operation to be carried out:

- Replace the accelerator cable.

Vehicles concerned:

- See vehicle types and fabrication cut-off details on title page.

When to take action:

- Upon receipt of a customer complaint and/or when the vehicle is first brought to the workshop.

Part required:

- 1 accelerator cable

Part number: according to Replacement Parts catalogue or Dialogys.

Tooling required:

- Conventional.

Description of the operation:

- Replace the accelerator cable with a new accelerator cable (A) (Fig. 1).




Fig. 1

A - New sleeve end piece

Marking the vehicle after the work has been carried out:

- Affix a new blue label, **Part No.: 49 39 031 070**, to the driver's side front shock absorber turret.
- Mark a cross in square **F1** using a marker pen.

	1	2	3	4	5	6
F	X					
G						
H						
I						
J						
K						

NOTE: The label, **Part No.: 49 39 031 070**, is available in sheets of 10 labels (delivered in packs of 10 sheets).

For UK Market:

Mark a cross in square **F1** using a marker pen.

NOTE: On current vehicles the matrix box is printed at the rear of the service booklet.

In the absence of the matrix box, affix a blue label, **Part No.49 39 031 070**, to the rear inside cover of the service booklet. Transfer previously marked squares to the new label and remove and destroy the old label.