



Type

CLIO 2

BB0 D

CB0 D

fitted with K7M engine and manual gearbox.

19 EXHAUST VIBRATES WHEN STATIONARY

Other sub-section concerned: 09

- Engine: K7M
- Gearbox: XXX

Basic manual:
– Workshop Repair Manual: 337

CUSTOMER COMPLAINT

- Exhaust vibrates when stationary.

POSSIBLE CAUSE

- Catalytic converter pipe vibrates.

CLAIM COMPLETION AND CODING

Destination of removed parts:

- As per Warranty Policy and Procedures Manual.

*Without Warranty Policy
and Service Contract*

NITG code: F135

*With Warranty Policy and
Service Contract*

Catalogue function: 044

Cause reference: 82 00 160 015

*With or without Warranty
Policy and Service
Contract*

Supplier code: T03

**Customer complaint
code:** 2G

Operation code: 1393

Total time allowed: 0.7 h

AFTER-SALES SOLUTION

Operation to be carried out:

- Replacement of the catalytic converter.

Vehicles concerned:

- See vehicle types shown on title page.

When to take action:

- Upon receipt of a customer complaint.

Part required:

- 1 catalytic converter **Part no: 82 00 160 015**

Tooling required:

- Conventional.

Description of the operation:

- Replace the catalytic converter.

"The repair methods given by the manufacturer in this document are based on the technical specifications current when it was prepared.

The methods may be modified as a result of changes introduced by the manufacturer in the production of the various component units and accessories from which his vehicles are constructed."

All copyrights reserved by Renault.

Copying or translating, in part or in full, of this document or use of the service part reference numbering system is forbidden without the prior written authority of Renault.